Quality Control Request Form

Sample Identification and Testing

TEST - XC, YM
CONTROL - XO, YP

rand: MARLBORO LONG SIZE Test Code: _____ Q.C. Code: _____

ate Received: 8/24/79 Report To: CG. BATES, J. NASH

est Objective: TO DETERMINE FTC TARS DILUTION, RTD, & PHYSICAL TESTING

ample Description: MARLBORO LS- CONTROL: SKIP TIP GLUE ROLLER & 33MM PLUG WRAP
TEST: PLAIN GLUE ROLLER & 33MM PLUG WRAP

o. of Test Samples: 1 (3 boxes) No. of Control Samples: 1 (3 boxes)

equested By: Judy Nash Mfg. Date: 8/23/79

ate Results Required: ASAP

amples From: S/S _____ Lville. _____ Mfg. Ctr. ✓

Q.C. Tests Required

moking and P.T.	✓	Coal Strength	
ieve		Picking	
all Mill		Cylinder Volume	
ack Moisture		Quality Audit	
ther, Specify			

R&D Tests Required

SAME AS ABOVE

2058083868

Results from Q.C.

T.P.M.:	Del.	Total R.T.D. Diluted:	
	Avail.	Total R.T.D. Undiluted:	
Water:	Del.	Total Plug Undiluted:	
	Avail.	Measured Dilution:	
icotine:	Del.	S.B.T.:	
	Avail.	Porosity:	
F.T.C.:	Del.	Circ.:	
	Avail.	Menthol:	
		Puff Count:	

Source: https://www.industrydocuments.ucsf.edu/docs/mtwy0004